

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10A




FIG. 10B






FIG. 10C




FIG. 11




FIG. 12A




FIG. 12B




FIG. 1 is a schematic diagram of a mechanical assembly 100. The assembly includes a large gear 181 at the top, a central gear 430, and a gear 410 on the left. A lever arm 180 is pivoted at 185 and has a contact point 160c. A curved member 14 with segments 14a and 14b is positioned below the lever. Other components include 11, 13, 420, 440, 450, 460, and 465.

FIG. 13B




FIG. 14A




FIG. 14B

